User Guide

MIXING: Mix equal parts of steel and hardener thoroughly with paddle or other suitable tool.

SURFACE PREPARATION: Clean surface of dirt, grease, oil, etc. Remove paint, primer or rust. For the best weld, roughen surface with file or coarse sandpaper.

APPLICATION: Apply J-8 Weld Industrial with suitable tool in an even coat, weld bead or extruded shape as needed.

DRYING: Allow 4-6 hours before handling and overnight (approximately 15 hours) before putting object back in use.

Faster drying will occur in a room with temperature over 50 F After curing for 6 hours, a heat lamp or light bulb can Co used to speed drying. In hot weather or warm room, let J-B Weld Industrial set up 15-20 minutes to thicken and prevent running or sagging.

WARNING: Harmful If swallowed. Eye Irritant May irritate skin causing allergic reactions.

CONTAINS: Modified Polyamine and Bisphenol-Apolyglycidyl ether.

PRECAUTIONS: Avoid ingestion. Keep away from eyes. Wash hands thoroughly with soap and water after use. KEEP OUT OF REACH OF CHILDREN.

FIRST AID: If swallowed, drink several glasses of water and get prompt medical advice. If eye contact occurs, flush eye for 5-10 minutes with water and seek medical attention. For further health information contact a poison control centre or J-B Weld.

Not recommended for usage in heating excess of 315 C or 600 F. Do not use near open flame. Use with adequate ventilation.